




DX Series Stainless Steel Press to Exit button on Metal Box

Model: ACRE-862C




Specs

Operating Voltage	9-13V DC
Material	Zink Alloy
Mechanical Life	1,000,000 Test
Sutable for Door	Hollow Door
Output Contact	COM, NC, & NO

Cable Diagram

- **COM:** This cable recive's signal from a device.
- **NO:** This cable sends the signal when the button is pressed.
- **NC:** This cable releases the signal when the button is pressed.



Connecting to DX AC Board

To connect this Push to Exit Button to the DX Access Control board please connect the following wires to the corresponding ports.

White Wire = PX Port

Red Wire = GRD Port

